

TLL COMPLEX REPAIRS OR EQUIPMENT

Sunday, March 14, 2021

15 Issues Identified



ISSUE 1

Charlton

Third base dugout no helmet rack



ISSUE 2

Charlton

Needs a homeplate



ISSUE 3

Charlton

Bleacher 2x4 lower knee braces need replace

Some silks on conc need replace



ISSUE 4

Senior league field

Unbolt flip boards



ISSUE 5

Seniors

Back stop needs replacing



ISSUE 6

Seniors

Third base bleachers , board replace, board reattach



ISSUE 7

Concession

One glass to be replaced in cases

Two new knee races needed under window counter



ISSUE 8

Baron first base bleachers one board to replace, couple boards to flip



ISSUE 9

Baron

Third base bleachers some boards to flip



ISSUE 10

Baron announcers booth one broken tread door threshold rotted, remove door fix floor reinstall caulk door



ISSUE 11

Baron

Announcers booth needs grip panel handrail



ISSUE 12

Baron bullpen 17' x 60' down need pipes and connectors



ISSUE 13

Rowson third base bleachers falling over needs to be pulled back and diagonal braces added



ISSUE 14

Rowson third base bleachers need 50% boards replaced and coated

ISSUE 15

Rowson mound and home plate batters box need to be rebuilt

Baron mound and home plate need to be rebuilt

Senior league mound and home plate need to be rebuilt